


# Spot Repair System



blue line

# Spot Repair System

## Produkt



### Systemkoffer

Zonder inhoud  
T9015.0000.1



### Handblok

Rond met microklittenband  
Ø 77 mm  
T8996.0000.1



### Intermediate pad

met microklittenband  
Ø 77 mm  
T8997.0000.8



### siacar 1941

siafast, Ø 80 mm  
P180/280/400/800  
T8998.xxxx.6

**Rodcraft Excenter  
Schuuruitslag  
2,5 mm, Incl. steun-  
schijf Ø 77 mm**



sia-Artikel-Nr.  
T8923.0000.1



### siamic 1990

siafast, Ø 80 mm  
Korrel P1200  
T8999.1200.6



### microtec 1790

siafast, Ø 80 mm  
Korrel 2000  
T6801.2000.6



### siavlies met siafast

Ø 80 mm, grijs  
Korrel 600  
T8995.0600.3



### Steunschijf

Ø 77 mm, 5/16"  
T9012.0077.1

## Krassen in de lak

RC-Excenter/Handblok  
siacar 1941/P400

Overgang van te repareren plek  
siacar 1941/P800  
met Intermediate pad

## Krassen met onderliggende roest

RC-Excenter/Handblok  
siacar 1941/P180 + P280

Overgang van te repareren plek  
siacar 1941/P400  
met Intermediate pad

## Deuk

RC-Excenter/Handblok  
siacar 1941/P180

Plamuur  
Voorschuren P180 + P280  
Naschuren P400  
met Intermediate pad

## Schuren van Filler

zonder Intermediate pad  
siacar 1941/P400 + P800

Naschuren met Intermediate pad  
siamic 1990/P1200

Overgang en spotbereik met RC-Excenter  
siavlies met siafast/K600 of microtc 1790/K2000 (vochtig)

**sia Abrasives Industries AG**

CH-8501 Frauenfeld  
E-mail: [sia.ch@sia-abrasives.com](mailto:sia.ch@sia-abrasives.com)  
[www.sia-abrasives.com](http://www.sia-abrasives.com)

